

IDEALIST LOGS MAINT AVION FULLBORE II
PLEASE PASS ASD/OEL 25X1A9a

- 1. SYSTEM 17 FLOWN I DEC FOR A FOUR HOUR HIGH, BUT FLIGHT ABORTED AFTER THREE HOURS DUE TO A MALFUNCTION IN THE MC RECORDER WHICH SHORT CIRCUITED THE PILOTS AUDIO LINE.

 POST FLIGHT ANALYSIS COMPLETED ON 3 DECEMBER INDICATES ALL RECEIVERS FUNCTIONAL. FREQUENCY CALIBRATION

 MARKERS ON THE SWEEP RECEIVERS STILL MARGINAL, ALTHOUGH SWEEPS APPEAR OFTEN ENOUGH TO PROVIDE PROPER RECEIVER CALIBRATION. STILL NO MARKERS ON THE 17B UNITS.
- 2. PREFLIGHT TESTS INDICATED SWEEPS OF 17B UNITS WERE ERMATIC. TECH REPS HAVE NO IDEA OF HOW TO TROUBLESHOOT.

 PROBLEM CURED ITSELF AS SHOWN BY POST FLIGHT ANALYSIS. AIRCRAFT COAX CABLING TO LEFT LOG PDC ANTENNA SHORTED, THUS ARTICLE FLEW WITH ONLY RIGHT LOG PDC ANTENNA OPERATIONAL. REPLACED "X" BAND UNIT WHOSE SENSITIVITY HAD DECREASED BY APPROX 15 DB

Approved For Release 2000/08/24 : CIA-RDP71B00263R000200290018-8
REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO.

Approved For Release 2000/08/24 : CIA-RDP71B00263R000200290018-8

25X1A6c

25X1A2d2

25X1A2d2

25X1A5a2

IN 77583 PAGE 8136 CECRET PAGE :

3. FOLLOWING SUMMARY BASED ON INPUTS FROM FOUR FLIGHTS. ONE AT

25X1A2d2

A. THE BASIC PROBLEM IS THE LACK OF SPECIALIZED EXPERIENCE

REQUIPED TO KEEP THE 17B UNITS OPERATING. THIS WAS ACCOMPLISHED

25X1A2d2 AT IN THE PERSON OF 25X1A5a2

B. A REVIEW OF THE PRESENT TEST PROGRAM SUGGESTS A SET UP SIMILAR
TO THAT EMPLOYED FOR THE 24 OCT TEST AT THIS PROVIDED 25X1A2d2
FOR THE 17B UNIT SPECIALIST PLUS TWO OTHER REPS WHO PERFORMED
"NORMAL" MAINTENANCE OF THE SYS 17 COMPONENTS AND THE RECORDERS,
AND WHO PERFORMED PREFLIGHT CALIBRATION. IT IS FELT, HOWEVER, THAT
AN ASSIST FROM AVIONICS CAN REDUCE BY ONE THE TOTAL NUMBER OF
PEPS PEQUIPED, PROVIDED OF COURSE, THAT THE 17B UNIT SPECIALIST
IS AVAILABLE.

- C. SYSTEM OPERATION AND RELIABILITY:
- 1. SWEEPING AND CRYSTAL VIDEO RECEIVERS HAVE OPERATED NORMALLY ON ALL FLIGHTS. CONTINUAL SOURCE OF TROUBLE HAS BEEN SWEEP FPEQUENCY MARKERS. RECORDED PREFLIGHT SWEEP CALIBRATION USING A SIG CEN HAS REDUCED THE EXTENT OF THE PROBLEM.
- 2. RECORDERS OPERATING PROPERLY. IMPOSSIBLE TO MONITOR DUPING RECORD DUE TO A.C. LINE PICK-UP, BUT NOISE OUTPUT LEVELS OF FLIGHT RECORDINGS ARE FAIRLY UNIFORM.
- 3. AIRCRAFT CABLING PROBLEMS STEMMED FROM LACK OF TIME FOR MAINTENANCE ON THE ARTICLE DUE TO HEAVY FLIGHT SCHEDULE.
 SHOPTED COAX MENTIONED IN PARA 2 ABOVE HAS BEEN REPAIRED.

Approved For Release 2000/08/24 : CIA-RDP71B00263R000200290018-8

Approved For Release 2000/08/24 : CIA-RDP71B00263R000200290018-8

25X1A6c

IN 77533

8136

0 2 0 1 E T

PAGE 3

- A. FOUR 17B MALFUNCTIONS TO DATE. SWEEP MARKERS, "L" BAND SWEEP DUE TO OVEN OVERHEATING, LOSS OF SENSITIVITY ON ONE "X"BAND UNIT, AND A BENCH CHECK OF THE SPAPE "S" BAND UNIT INDICATES EXTREMELY NON-LINEAR SWEEP.
- D. MAINTENANCE AND SPARES. LACKING SCHEMATICS AND MANUALS, THE 17B UNITS CANNOT BE MAINTAINED IN SAME FASHION AS THE 17 RECEIVERS, WHEPEIN A SPARE UNIT IS UTILIZED WHILE MALFUNCTIONING UNIT IS REPAIRED IN THE SHOP. "L" BAND UNIT STILL NOT ON HAND. PLEASE EXPEDITE.
 - E. TAPE SITUATION: 6 REELS VIPGIN. 20 REELS ERASED.
- 4. PESULTS TO DATE INDICATE PRESENT TECHNICAL SUPPORT INADEQUATE TO KEEP UP WITH SYS 17B FAILURES. THE FOUR MALFUNCTIONS OF ABOVE, PLUS LACK OF SPARE "L" BAND RECEIVER HAVE REDUCED SYSTEM EFFECTIVENESS TO A MARGINAL CONDITION. ANY FURTHER MAJOR RECEIVER FAILURES WOULD ELIMINATE COVERAGE OF A COMPLETE BAND OF INTEREST. RECOMMEND EXPEDITE SENDING THE SYS 17B SPECIALIST SOONEST.

25X1A5a1

5. THE TEST FLIGHT ORIGINALLY SCHEDULED FOR 6 DEC MAY BE DELAYED

DUE TO OPERATIONAL REQUIREMENTS. ALSO, IT APPEARS AT THIS TIME THAT

ADDITIONAL TEST FLIGHTS MAY BE REQUIRED BEFORE CAN SAY WITH ANY

ASSURANCE THAT THE SYSTEM 17 IS OPERATIONALLY READY. 25X1A2d2

CE 9-P B T TOP: 040720Z DEC 67